














WOHNLING®

Möbel zum Wohlfühlen

WL1.709
 WL1.710
 WL5.018



 <p>A*1</p>	 <p>B*1</p>	 <p>C*4</p>	 <p>D*8</p>	 <p>E*4</p>	 <p>F*8</p>	 <p>G*8</p>	 <p>H*4</p>	 <p>I*1</p>
<p>①</p>  <p>Diagram showing the base frame (B) and legs (C) being attached. Screws (D) and washers (F) are used to secure the legs to the base frame.</p>	<p>②</p>  <p>Diagram showing the top panel (A) being attached to the base frame. Screws (E) and washers (G) are used to secure the top panel to the base frame.</p>	<p>③</p>  <p>Diagram showing the final assembly step where the L-bracket (I) is attached to the base frame to provide additional stability.</p>						